

Oil Field Environmental Incident Summary

Incident: 20151217095207 **Date/Time of Notice:** 12/17/2015 09:52

Responsible Party: HRC OPERATING, LLC

Well Operator: HRC OPERATING, LLC

Well Name: BORRUD 156-101-2B-11-3H

Field Name: TYRONE

Well File #: 29238

Date Incident: 12/16/2015 **Time Incident:** 08:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 101

Sec: 2

Qtr:

Location Description:

Submitted By: Julia Traster

Received By:

Contact Person: Chris Martinez
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	55	Barrels	55	Barrels	55	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/20/2016

Clean Up Concluded: 12/17/2015

Risk Evaluation:

There were no personal injuries.

Areal Extent:

Potential Environmental Impacts:

No impacts to surface or groundwater. All released oil remained on the facility location. 50 barrels of oil remained within the tank battery secondary containment. 5 barrels of oil remained on the facility in the site perimeter ditch.

Action Taken or Planned:

Summit was called to the location to make necessary repair to the LACT system. Halcon automation personnel made repairs to the automation system. T&R was called to pick up all free oil and wash down the spill area.

Wastes Disposal Location: Oil was returned to the tanks. Waste materials will be disposed of at an approved landfill.

Agencies Involved:**Updates**

Date: 12/17/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.